

1998 Prevost Country Coach upgrade/service history

REFIT:

Complete length SIDE RAILS and REAR AIR DAM update of Coach	(2010)
Complete Prevost Specification Roof Removal and Refurbishment (Freightliner / Houston Body Shop)	(2014)
Exterior Paint Maintained and refurbished by Freightliner Paint & Body Shop	
Driver and Passenger Captain Chairs (Ultra leather)	(2017)
Driver's side window completely replaced (double pane)	(2017)
Front suspension:	
Remove and replace Upper and lower control Arms	(2017)
Replace Front Air Bags	(2017)
Left and Right Drive axle seals replaced	(2017)
Rear Drive axle brake assemblies replaced	(2017)
Main Engine Radiator NEW Replaced (Prevost Spec's)	(2017)
Complete Radiator Clutch Assembly	(2017)
Complete refurbish of radiator structure / refinish	(2017)
Complete Water Bay rebuild:	
New insulated bay and floor rebuild	(2017)
Two new 11.5 Gallon Acuuma Water heaters	(2017)
Two new high-volume water pumps	(2017)
Generator Radiator removed and replaced (NEW)	(2017)
Generator Starter replaced (NEW)	(2017)
Head Lights (NEW)	(2017)
Bay Door docking lights hard wired LEDS (48 LEDS/ Light)	(2017)
Emergency LED STOP Light	(2017)
Front Windshield replaced	(2017)
Replaced with high volume Auxiliary Air Compressor	(2017)
Insulated Air Compressor bay	(2017)
Insulated Tool Compartment Bay	(2017)
Zip Dee Awning LOCK replacements (both ends)	(2017)
Tires and House / Chassis Batteries in excellent condition	