

<b>8/15/07</b>	<b>Buddy Gregg - Dallas</b>	<b>Replace three roof ac units (Dometic 630516-331)</b>
<b>5/21/08 MI97246</b>	<b>Desert West Coach</b>	<b>Replaced fan clutch</b>
		<b>Replaced 50DN regulator</b>
<b>9/18/09</b>	<b>Buddy Gregg - Dallas</b>	<b>Replace brake chambers</b>
		<b>Full transmission service</b>
<b>10/12/09 MI 125246</b>	<b>Prevost Nashville</b>	<b>Fuel tank sending unit gasket</b>
		<b>Install belt tensioner update kit</b>
		<b>Transmission output shaft seal</b>
		<b>Remove and replace right windshield</b>
<b>11/02/09 MI 126338</b>	<b>Prevost Nashville</b>	<b>Replace rubber hoses in engine compartment</b>
		<b>Replaced all small vent lines</b>
		<b>Air dryer service</b>
		<b>Replaced upper A-Arms ball joints</b>
		<b>upper A-Arm tie rods and relay rod ends</b>
		<b>Replaced Lower A-Arm sealing boots</b>
		<b>Replaced mini lobe on fan drive</b>
<b>8/11/10 MI 136268</b>	<b>Prevost Nashville</b>	<b>Replaced windshield wiper arm assemblies</b>
		<b>Replaved CC OTR AC compressor hoses</b>
<b>9/09/10 MI 143067</b>	<b>Prevost Fort Worth</b>	<b>Replaced all suspension air bags</b>
		<b>Replaced all Norgen valves</b>
		<b>Ck all wheel seals - good</b>
		<b>Ck all brakes - good replaced two slide pin boot covers</b>
		<b>Service transmission</b>
		<b>Cleaned out fuel sending unit and replaced gasket</b>
<b>11/1/10 MI 145589</b>	<b>Prevost Jacksonville</b>	<b>Replaced 8 tires</b>
		<b>Installed SmarTire Kit</b>
		<b>Replaced left drive hub seal</b>
		<b>Replaved right tag hub seal</b>
<b>11/05/10 MI 147582</b>	<b>Prevost Fort Worth</b>	<b>Install new muffler and hangers</b>
		<b>Level 3 service</b>
<b>10/17/11 MI 170548</b>	<b>Prevost Fort Worth</b>	<b>Level 3 service</b>
		<b>R&amp;R right tag and replace slide pin boots adjusted all brakes</b>

		Replaced right tag hub oiler
		R & R CC OTR compressor and replace hoses and compressor
		Replaced all shocks
3/27/11	MI 155024	Russell Coach Works
		Replaced genset conduit and repair
		Ck house batteries 1 & 5 weak
		Replaced Wabasto fuel pump, fuei nossel,
		ignitor electrodes and filters
2/1/12		Xtreme Paint & Graphics
		Replace house batteries (Nick Hessler)
6/7/12		A & E Generator
		Replace 50DN altenator
02/20/12	MI 175825	Prevost Fort Worth
		Repair Wabasto ignition coil, thermostat and grommets
3/30/12	MI 178216	Prevost Fort Worth
		Level 3 service
		Adjusted left steer axel bearing retainer nut
4/10/12	MI 179218	Prevosts Fort Worth
		R & R both front torque bars
7/10/12	MI 184563	Prevosts Fort Worth
		Level 2 service
		Service CC OTR AC compressor too much refrigerant
10/16/13	MI 202161	Prevost Fort Worth
		Level 3 service
		R & R right front and right tag shocks (leaking)
		R & R Air dryer assembly (Wabco S1200 24 VDC)
10/23/13	MI 203798	Prevost Fort Worth
		Replace air compressor (TF 750 REMAN)
		Air D2 governor
		Replace exhaust flex pipe on engine
		Replace fan clutch
		Removed radiator shroud and tightend leaking clamp
7/08/14	MI 212990	Prevost Fort Worth
		Level 3 service
		Oil Analassys good
		Replaced right steer wheel seal
		Replaced all shocks
		Replace transmission output shaft seal and yoke
		Replaced bell crank grease caps
		Replace lower a-arm and do 3 axel alignment

<b>3/25/14</b>	<b>MI 207300</b>	<b>TCI Shreveport LA. (Michelin Tires)</b>	<b>Replace all 8 tires and install Pressure Pro Sensors</b>
<b>6/12/14</b>	<b>MI 211973</b>	<b>East Tennessee Luxury Coach LLC</b>	<b>Replaced two front Norgen valves</b>
<b>7/13/15</b>	<b>M214,400</b>	<b>East Tennessee Luxury Coach LLC</b>	<b>Replace all Norgren valves Replace dash A/C compressor</b>
<b>8/10/15</b>	<b>M214,400</b>	<b>East Tennessee Luxury Coach LLC</b>	<b>Rebuild and recover both front seats</b>
<b>8/17/15</b>		<b>Self/ Curry's AC and Alignment</b>	<b>Replace Country Coach OTR A/C compressor</b>
<b>9/8/15</b>		<b>Self/Prevost Houston</b>	<b>Replace Vanner Equalizer</b>
<b>10/12/15</b>		<b>Self/Elreg</b>	<b>Replace chassis 24v alternator</b>
<b>10/20/15</b>		<b>Prevost Fort Worth</b>	<b>Replace all brake relay valves 3-R12's, 1- R14 Replace Transmission output shaft seal Replace air dryer assembly Wabco S1200 24v</b>
<b>10/20/15</b>		<b>Self/Heavy Truck Parts</b>	<b>Replaced all upper marker lights with LED</b>
<b>10/21/15</b>		<b>East Tennessee Luxury Coach LLC</b>	<b>Level 3 Service, Differential service, Transmission service with Transend Fluid and Replace air dryer cartridge</b>
<b>2/15/16</b>		<b>East Tennessee Luxury Coach LLC</b>	<b>Replaced All 4 front side windows, Replace Water Heaters, Replaced Replaced several drain cocks for air leaks, Replace Ride Height Valve</b>
<b>6/8/16</b>		<b>Zipp Dee Awnings</b>	<b>Repair and Return Front Arm</b>
		<b>Zipp Dee Awnings</b>	<b>Order New Motor Assembly</b>
		<b>Zipp Dee Awnings</b>	<b>Repair and Return Front Arm</b>
<b>6/9/16</b>		<b>East Tennessee Luxury Coach LLC</b>	<b>Repair Air Leaks, Replace 50DN Seal, Install Awning Arm</b>
<b>10/20/16</b>		<b>Prevost FW</b>	<b>Replace Two Front Hub Seals</b>
<b>11/10/16</b>		<b>Self/Safety Products Inc.</b>	<b>Replace Reverse Alarm</b>

<b>11/14/16</b>	<b>Prevost JAK</b>	<b>Level 3 Service, Replace Ground Strap</b>
<b>11/22/16</b>	<b>East Tennessee Luxry Coach LLC</b>	<b>Replace Dog Bone Bushings, Left Drive Axel Seal</b>
<b>11/25/16</b>	<b>East Tennessee Luxry Coach LLC</b>	<b>Replace Starter &amp; Solenoid with Mitsubishi, Replace Webasto Fuel Nozzel, install 4 Nevis LED Lights</b>
<b>11/26/16</b>	<b>Self</b>	<b>Replace House Water Pump/Remco Pump 5503-AV15-B636</b>
<b>2/15/17</b>	<b>Xtreme Paint &amp; Graphice</b>	<b>Install Roof Coating/Repair Left Rear Wheel Opening</b>
<b>4/5/17</b>	<b>Self/ZipDee</b>	<b>Recharge and replace rafter arms</b>
<b>4/12/17</b>	<b>Self/NAPA</b>	<b>Replace Chassis Batteries</b>
<b>4/12/17</b>	<b>Self/ETLC/TransSpecialest</b>	<b>Replace House Batteries (6) 8D</b>
<b>4/28/17</b>	<b>Self/ETLC</b>	<b>Replace Inverters with Magnum MS2812 Pure Sine Wave</b>
<b>7/3/17</b>	<b>ETLC</b>	<b>Replace Racor Filter, Add Racor Filter For Webasto Replace 50 DN Alternator w/ Air Cooled Elrig 330 Amp</b>
<b>7/11/17</b>	<b>Self</b>	<b>Replace House Alternator Regulator with Balmar MC-614H 3 Stage Regulator</b>